Approved For Release 2002/10/24 : CIA-RDP67B00820R000200030015-5

6 FEB 64 17 CLASSIFIED MESSAGE

S-E-C-R-E-T

25X1A [redacted] ab
ORIG:
UNIT: MD/OSA-DD/S&T
EXT: 5709
DATE: 5 FEBRUARY 1964

25X1A TO : [redacted]

FROM: DIRECTOR

CONF:

INFO: OSA 1-15

ROUTING			
1	MD/OSA	9	SSD/OSA
2	AD/OSA	10	D/Tech
3	D/FA/OSA	11	
4	IDEA/FA	12	
5	CC/FA	13	
6	RB/OSA	14	
7	CD/OSA	15	
8	SS/OSA	16	

PRECEDENCE				
	DEFERRED		PRIORITY	INITIALS
X	ROUTINE		OPERATIONAL IMMEDIATE	INITIALS

40101

25X1A TO [redacted] 25X1A INFO [redacted] 25X1A CITE [redacted] 0737

IDEALIST LOGS

REF: TRIP REPORT, DATED 30 JAN 64, 25X1A [redacted]

1. INDICATIONS ARE THAT THE DAYTON PROCESSOR S/N 8 PRESENTLY ON 25X1A LOAN [redacted] IS IN DEPLORABLE CONDITION. APPRECIATE THE COOPERATION AND ASSISTANCE YOUR PEOPLE RENDERED IN MAKING THIS UNIT TEMPORARILY SERVICEABLE DURING MODIFICATION AND UPDATING S/N 2. CAN YOU FURNISH ESTIMATED COST TO REPAIR AND UPDATE S/N 2?

2. REF LAST PARA PAGE 3 OF SUBJECT REPORT, WITH REGARD TO 25X1A VERSAMAT. NOT SURE WHETHER YOU SENT SALESMAN OR ENGINEER TO [redacted] HOWEVER WOULD APPRECIATE BROCHURE ON THE VERSAMAT AND YOUR UNBIASED OPINION AND RECOMMENDATIONS FOR USE OF THIS ITEM IN THE FIELD. WOULD IT REPLACE ANY EQUIPMENT PRESENTLY IN USE, I.E. THE 70MM DAYTON PROCESSOR AND THE EH6A, ETC? WHAT BENEFITS WOULD BE DERIVED PRODUCT IMPROVEMENT WISE AND WOULD THIS EQUIPMENT REQUIRE MORE SPACE THAN EQUIPMENT PRESENTLY IN USE? WHAT IS PRESENT AVAILABILITY OF VERSAMAT AND PRICE? WOULD APPRECIATE THIS INFORMATION BEFORE WE PROCEED WITH 25X1A EQUIPMENT REPAIR AND UPDATING AS REFERENCED IN SUBJECT REPORT. SSD/OSA

END OF MESSAGE

[redacted]
RELEASING OFFICER

COORDINATING OFFICERS
S-E-C-R-E-T

SS/OSA IDEA/FA
CD/OSA
AUTHENTICATING OFFICER

GROUP 1 Excluded from automatic downgrading and declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No. 9

Approved For Release 2002/10/24 : CIA-RDP67B00820R000200030015-5